

Inspection Report

This report is created by

LAUNCH

Vehicle Information

VIN: 1FTNF1EF0CKE01760
Vehicle manufacturer/model: EOBD/F-150
Year of manufacture: 2012
Vehicle Software Version: V23.12
Repair State: 1

Inspection Result

There are 3 issues for Vehicle body system:

- 1.Inductive Signature Chip Communication Error
- 2.Throttle Actuator Control Module Processor
- 3.Internal Control Module Software Incompatibility

Professional Report

EOBDAbnormal 3

DTC Qty (3)

P1636	Inductive Signature Chip Communication Error	Pending
P2107	Throttle Actuator Control Module Processor	Pending
U0300	Internal Control Module Software Incompatibility	Pending

Disclaimer

This inspection report is for reference only. All data provided in this report is based on static data, detailed dynamic and/or live diagnostic data should be generated by a professional maintenance tool. Launch is not liable for any fault or accident caused thereby.